



KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No. 14/2018.

East Coast of England - The Wash

Approaches to Kings Lynn

Amendments to Buoyage

Mariners are advised that due to changes in the profile of the approach channel the following amendments will take place on or about 2nd May 2018:

- a) No.8 light buoy to be moved to 52° 52'.795 N 00°21'.675E
- b) No.10 light buoy to be moved to 52° 52'.560 N 00°21'.900E
- c) No.12 light buoy to be moved to 52° 52'.335 N 00°21'.890E
- d) No.7 light buoy to be moved to 52° 52'.825 N 00°21'.455E
- e) No.11 light buoy to be moved to 52° 52'.530 N 00°21'.715E
- f) No.13 light buoy to be moved to 52° 52'.275 N 00°21'.715E

See attached chart extract showing proposed changes to buoyage.

Mariners are advised that commercial shipping may be encountered outside of the buoyed channel in this vicinity until the buoys are moved.

Mariners are requested to give the buoying vessel "St Edmund" a wide berth and pass at minimum speed whilst works to move the buoys are being undertaken.

For further information please contact King's Lynn Harbour Radio on VHF 14.

27th April 2018.

P.M Bailey.

Deputy Harbour Master.

King's Lynn,

Norfolk PE30 ILL

www.kingslynnport.co.uk

