

## KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No. 14/2020.

East Coast of England - The Wash

Approaches to King's Lynn

## Collapse of Beacon

Mariners are advised that Beacon B, (52°49.'090 N 00° 21.136 E) has collapsed following collision by a vessel and is no longer operational.

An area of 10 metres radius centred on the above position is foul and unmarked.

Mariners are requested to give this area a wide berth until works to remove the debris and replace the beacon are completed

For further information please contact King's Lynn Harbour Radio on VHF 14.

20<sup>th</sup> April 2020

P.M Bailey. Deputy Harbour Master. King's Lynn, Norfolk PE30 ILL www.kingslynnport.co.uk