



KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No. 25/2020.

East Coast of England - Approaches to the Wash.

Race Bank Offshore Wind Farm Export Cables
Area of Export Cable Exposure at Seafloor

Charts BA1200, BA108 and Imray Y9

As Competent Harbour Authority the KLCB is responsible for managing the safe operation of navigation and other marine activities in the harbour and its approaches.

Mariners are advised that the most recent survey within the port jurisdictions (KP3 to KP28.5) of the export cables of the Race Bank OWF have indicated a single possible cable exposure at seafloor on the southern export cable at KP23.295.

The possible cable exposure was identified in data collected in July 2020. The exposure was observed to be 5.8 m long and centred at the following position:

- WGS UTM31N: 324,118mE, 5,875,075mN
- Lat/Long (decimal degrees): N 52.99632, E 0.37918
- Lat/Long (DMS): N 52° 59' 46.766", E 0° 22' 45.063"

KLCB has established the following navigational buoys that is strategically placed along the cable route to mark the zone and enhance spatial awareness for mariners;

Z9 buoy, position 52° 59'.735N 00° 22'.750E FI (2) 6s.

Figure 1 presents the location of the possible cable exposure.




Figure 1: Location of possible cable exposure in relation to The Wash and Race Bank export cables

For more information, contact Diamond Transmission Partners RB Limited using contact details below.

Brian Critchley, Geo-4D Ltd (acting on behalf of Diamond Transmission Partners RB Limited)

□ Email: brian.critchley@geo-4d.com

□ Tel: +44 (0) 345 257 0877

30.11.2020

P.J.Jary

Harbour Master.

Harbour Office,

King's Lynn,

Norfolk PE30 ILL

www.kingslynnport.co.uk