



**KING'S LYNN CONSERVANCY BOARD.**

Notice to Mariners 20/ 2018.

East Coast of England - The Wash

King's Lynn Harbour.

Beacon "Bravo" Navigational Mark

Temporary Mark established

BA 1200 Y9

Mariners are advised that on Navigational Mark Beacon "Bravo" has been replaced with a temporary mark and has a light characteristic of Fl.Y.2s.

Beacon "Bravo" position 52° 49'.090N 000° 21'.136E.

Mariners are advised to keep a good lookout in this area.

3<sup>rd</sup> July 2018.

P.J.Jary.

Harbour Master.

King's Lynn,

Norfolk PE30 ILL

[www.kingslynnport.co.uk](http://www.kingslynnport.co.uk)