

KING'S LYNN CONSERVANCY BOARD.



Notice to Mariners No. 14 / 2021

East Coast of England - The Wash

Approaches to King's Lynn

Re-Establishment of East Stones Light Buoy .

New Position

Mariners are advised the East Stones Light Buoy will be re-established on about 8th June 2021 in the following position. 52° 48.122' N 00° 21.655' E

Please note that this position is approx 20m to the west of the last charted position.

NtM 11/2021 is now cancelled.

Please contact the Harbour Office for further information.

7th June 2021

P M Bailey
Deputy Harbour Master.
Harbour Office,
King's Lynn,
Norfolk PE30 1LL
T: 01553 773411
www.kingslynnport.co.uk