

## KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No. 05/2024.

East Coast of England - The Wash

Approaches to Kings Lynn.

Alterations & additions to Buoyage: Nos 21, 22, 23 & "B" buoys.

Mariners are advised that due to changes in the approach channel the following alterations to buoyage has been completed on 18.03.24.

- a) No 22 (Fl Q. Red) Light buoy moved to Lat 52° 50.419'N Long 000° 21.833'E.
- b) No 21 (Fl(2) G 4s) Light buoy moved to Lat 52° 50.391'N Long 000° 21.724'E.
- c) No 23 (Fl G 3s) Light buoy moved to Lat 52° 50.225'N Long 000° 21.758'E.
- d) "B" buoy (Fl Yellow 2s) established in position Lat 52° 50.538'N Long 000° 21.705'E.

This NTM cancels 04/2024.

18.03.24

P.J.Jary.
Harbour Master.
King's Lynn,
Norfolk PE30 ILL
www.kingslynnport.co.uk