



KING'S LYNN CONSERVANCY BOARD.

Notice to Mariners No. 10/2026.

East Coast of England - The Wash

Approaches to Kings Lynn.

Alterations to Buoyage: Nos 21 & Tango light buoys.

Mariners are advised that the below changes to buoyage in the approach channel buoyage will be completed on 02.06.26.

- a) No 21 Light buoy new location - Lat 52° 50.590'N Long 000° 21.640'E.
- b) No Tango Light buoy new location- Lat 52° 50.676'N Long 000° 21.664'E.

Workboat St Edmund will be completing the operations and will be Restricted in her ability to manoeuvre.

Mariners should keep clear of St Edmund and pass at a safe and reduced speed. St Edmund will be monitoring VHF CH 14 & 16.

02.06.2026

Harbour Master.

King's Lynn Conservancy Board.

King's Lynn,

Norfolk PE30 ILL

[www.kingslynnport.co.uk](http://www.kingslynnport.co.uk)