

52°50'.80N

**Issue Date: 5th April 2024**

**Date of Survey: 4th April 2024**

00° 21'.00 E

00° 21'.80 E

00° 22'.20 E

NW By FLY 5s

52° 50'.40 N

Bravo buoy

No.22 Buoy

No.21 Buoy

No.23 Buoy

Outline of Disposal area May 2023



1m above Dock sill

Dock sill

Approx Eastern Limit of spoil ground

### PORT of KING'S LYNN

DATUM:  
Chart Datum Hunstanton  
(Dock Sill)

Every endeavour is made to ensure the accuracy of the information given at the time of the the survey, but King's Lynn Conservancy Board cannot accept any liability whatsoever for the consequences of any inaccuracies shown, however caused.

The information given on this drawing is only valid for the day of the survey

Depths in Metres:  
Where underlined, then above dock sill

52° 50'.00 N

No.24 Buoy

West Stones  
Bcn



Z Bcn

52° 49'.60 N

### Spoil Ground Area

